MEMBRANE RESTORATION

Millennium Single-Ply Bonding Adhesive EPDM/TPO



DESCRIPTION

Millennium Single-Ply Bonding Adhesive is a solvent based contact adhesive formulated to adhere EPDM and TPO.

BASIC USE

Adheres EPDM and TPO roofing membranes to wood, metal flashings, brick or block masonry, rooftop flashings, insulation, recover, barrier boards, and other acceptable substrates.

APPROVED SUBSTRATES

- Wood
- Metal flashings
- Brick or block masonry
- Rooftop flashings
- Insulation
- Recover
- Barrier boards

APPROVED MEMBRANES

EPDM and TPO.

COLOR

Yellow

SURFACE PREPARATION

All surfaces to be adhered should be thoroughly dry, clean, and free of dust and loose debris. Membranes and substrates should be free of oil, grease, and other contaminants.

SAFETY

Do not use in a confined space or around heat, flame or sparks. Prevent fumes from entering building via air ventilation ducts. Avoid breathing adhesive vapors. Wear safety glasses or goggles to prevent contact with eyes. Wear gloves that meet ANSI/ISEA 105-2005 to protect when applying adhesive. Keep out of the reach of children. Read Safety Data Sheet for complete safety information before use. Do not smoke when applying this product.

LIMITATIONS

- Not for use on PVC or KEE membranes.
- Do not apply to wet or damp surfaces. This includes primers.
 Allow solvent based primers to completely dry before using the adhesive.
- Do not apply when surface temperatures are below 40°F (4°C).

EQUIPMENT

- Solvent resistant paint roller
- Spray rigs designed to apply adhesives
- Commercially available adhesive dispensers

FEATURES	BENEFITS
High-strength adhesive	Maintains integrity of installed membrane for years
Excellent adhesive performance	Compatible with a wide range of substrates
Fast application	Labor savings for contractor

CAUTION: All statements and technical information in this document are based on tests or data that H.B. Fuller believes is reliable. However, H.B. Fuller does not warrant or guarantee the accuracy or completeness of this information. The user has sole knowledge and control of factors that can affect the performance of H.B. Fuller's products in the user's intended application. It is the user's responsibility to conduct tests to determine the compatibility of H.B. Fuller's product with the design, structure, and materials of the user's end product and the suitability of H.B. Fuller's product for the user's method of application and intended use. The user assumes all risk and liability arising out of such use.



APPLICATION

- Thoroughly stir the adhesive before and during use. Do not use electric
 drills to mix the adhesive. Do not thin adhesive. Thinning will affect
 adhesive performance. The color should be consistent with no solids
 remaining on the bottom.
- 2. Millennium Single-Ply Bonding Adhesive is a contact adhesive that needs to fully "flash-off" before the membrane and substrate surface are joined together. To ensure the adhesive flash-off time is approximately the same, apply the Bonding Adhesive to both surfaces in one application. Bonding Adhesive can be applied using a solvent resistant paint roller, spray rigs designed to apply adhesives or commercially available adhesive dispensers. If the adhesive is spray applied, it is recommended to roll the adhesive with a solvent resistant roller.
- 3. Position the membrane into place and allow adequate time for the membrane to relax.
- 4. "Barn Door" fold the membrane onto itself exposing the substrate and bottom of the membrane. Apply the adhesive in a uniform and consistent coat; avoiding globs and puddles and light areas. Make sure not to apply bonding adhesive over areas which will be used to create field or flashing seams.
- 5. Allow the adhesive to fully flash-off and become tacky. Using the fingerpush method, check the adhesive by applying pressure with a finger to the adhesive while pushing across the adhesive.
- After adequate flash-off time, roll the membrane onto the adhesive coated substrate and immediately brush the membrane with a stiff bristle broom to ensure maximum contact.

STORAGE

- 1. Store in original unopened containers at temperatures between 60°F and 80°F.
- When stored in cooler temperatures, allow material to warm to room temperature before using.
- 3. Do not allow material to be stored in direct sunlight.
- 4. Rotate stock. Do not use product past 12 month shelf life.

SHELF LIFE

- When stored in original unopened containers at temperatures between 60°F (15.6°C) and 80°F (26.7°C), a shelf life of 12 months can be expected.
- The expected shelf life can be shortened if product is stored in temperatures exceeding recommended storage levels.

PACKAGING AND COVERAGE

Millennium Single-Ply Bonding Adhesive is available in the following package:

Pails Size	<u>Part #</u>	Pails/Pallet
5 Gallon (18.9L)	SB12982-902	45
5 Gallon (18.9L)	SB12982-903 (EU)	45

A coverage rate of 45 to 60 sq. ft. (4.18 to 5.57 m²)of finished roof, per gallon, should be expected. Coverage rates will vary depending upon the type of substrate and substrate surface. Some substrates are more porous and will absorb more adhesive resulting in a lower coverage rate. Other substrates have smooth dense facers resulting in a higher coverage rate. Coverage rates are based on applications using a 3/8 inch solvent based paint roller cover.



For more information about our company, visit www.hbfuller.com/roofing.

