Oldcastle BuildingEnvelope


275 Britannia Road East ▪ Mississauga ▪ Ontario ▪ Canada ▪ L4Z2E7
905-890-6970 ▪ obe.com

6500 SERIES UNITIZED CURTAIN WALL STANDARD SYSTEM DETAILS

7" BACKSECTION SYSTEM 1-3/4" GLAZING


Drawn By:	AG	**Date:**	2026/09/29	**Number of Sheets:**	28

6500 SERIES UNITIZED CURTAIN WALL - 7" BACK SECTION - 1 3/4" GLAZING




VERTICAL MULLION SSG
AT VISION BESIDE VISION

6500 SERIES UNITIZED CURTAIN WALL - 7" BACK SECTION - 1 3/4" GLAZING




VERTICAL MULLION SSG
AT SPANDREL BESIDE SPANDREL

6500 SERIES UNITIZED CURTAIN WALL - 7" BACK SECTION - 1 3/4" GLAZING




VERTICAL JAMB SSG
AT VISION GLAZING

6500 SERIES UNITIZED CURTAIN WALL - 7" BACK SECTION - 1 3/4" GLAZING




VERTICAL JAMB SSG
AT SPANDREL GLAZING

6500 SERIES UNITIZED CURTAIN WALL - 7" BACK SECTION - 1 3/4" GLAZING




VERTICAL MULLION CAPPED AT VISION BESIDE VISION

6500 SERIES UNITIZED CURTAIN WALL - 7" BACK SECTION - 1 3/4" GLAZING




VERTICAL MULLION CAPPED
AT SPANDREL BESIDE SPANDREL

6500 SERIES UNITIZED CURTAIN WALL - 7" BACK SECTION - 1 3/4" GLAZING




VERTICAL JAMB CAPPED AT VISION GLAZING

6500 SERIES UNITIZED CURTAIN WALL - 7" BACK SECTION - 1 3/4" GLAZING




VERTICAL JAMB CAPPED AT SPANDREL GLAZING

6500 SERIES UNITIZED CURTAIN WALL - 7" BACK SECTION - 1 3/4" GLAZING




EXPANSION HORIZONTAL SSG
AT VISION OVER SPANDREL

6500 SERIES UNITIZED CURTAIN WALL - 7" BACK SECTION - 1 3/4" GLAZING




EXPANSION HORIZONTAL SSG
AT VISION OVER VISION

6500 SERIES UNITIZED CURTAIN WALL - 7" BACK SECTION - 1 3/4" GLAZING




INTERMEDIATE HORIZONTAL SSG
AT VISION OVER VISION

6500 SERIES UNITIZED CURTAIN WALL - 7" BACK SECTION - 1 3/4" GLAZING




INTERMEDIATE HORIZONTAL SSG AT SPANDREL OVER VISION

6500 SERIES UNITIZED CURTAIN WALL - 7" BACK SECTION - 1 3/4" GLAZING




EXPANSION HORIZONTAL CAPPED AT VISION OVER SPANDREL

6500 SERIES UNITIZED CURTAIN WALL - 7" BACK SECTION - 1 3/4" GLAZING




EXPANSION HORIZONTAL CAPPED AT VISION OVER VISION

6500 SERIES UNITIZED CURTAIN WALL - 7" BACK SECTION - 1 3/4" GLAZING




INTERMEDIATE HORIZONTAL CAPPED AT VISION OVER VISION

6500 SERIES UNITIZED CURTAIN WALL - 7" BACK SECTION - 1 3/4" GLAZING




INTERMEDIATE HORIZONTAL CAPPED AT SPANDREL OVER VISION

6500 SERIES UNITIZED CURTAIN WALL - 7" BACK SECTION - 1 3/4" GLAZING




HEAD HORIZONTAL SSG AT VISION GLAZING

6500 SERIES UNITIZED CURTAIN WALL - 7" BACK SECTION - 1 3/4" GLAZING




HEAD HORIZONTAL SSG AT SPANDREL GLAZING

6500 SERIES UNITIZED CURTAIN WALL - 7" BACK SECTION - 1 3/4" GLAZING




HEAD HORIZONTAL CAPPED AT VISION GLAZING

6500 SERIES UNITIZED CURTAIN WALL - 7" BACK SECTION - 1 3/4" GLAZING




HEAD HORIZONTAL CAPPED AT SPANDREL GLAZING

6500 SERIES UNITIZED CURTAIN WALL - 7" BACK SECTION - 1 3/4" GLAZING




SILL HORIZONTAL SSG ON STARTER TRACK AT VISION GLAZING

6500 SERIES UNITIZED CURTAIN WALL - 7" BACK SECTION - 1 3/4" GLAZING




SILL HORIZONTAL SSG ON STARTER TRACK AT SPANDREL GLAZING

6500 SERIES UNITIZED CURTAIN WALL - 7" BACK SECTION - 1 3/4" GLAZING




SILL HORIZONTAL CAPPED ON STARTER TRACK AT VISION GLAZING

6500 SERIES UNITIZED CURTAIN WALL - 7" BACK SECTION - 1 3/4" GLAZING




SILL HORIZONTAL CAPPED ON STARTER TRACK AT SPANDREL GLAZING

6500 SERIES UNITIZED CURTAIN WALL - 7" BACK SECTION - 1 3/4" GLAZING




90° OUTSIDE CORNER MULLION SSG AT VISION GLAZING

6500 SERIES UNITIZED CURTAIN WALL - 7" BACK SECTION - 1 3/4" GLAZING




90° OUTSIDE CORNER MULLION SSG AT SPANDREL GLAZING

6500 SERIES UNITIZED CURTAIN WALL - 7" BACK SECTION - 1 3/4" GLAZING



90° OUTSIDE CORNER MULLION CAPPED AT VISION GLAZING

6500 SERIES UNITIZED CURTAIN WALL - 7" BACK SECTION - 1 3/4" GLAZING



90° OUTSIDE CORNER MULLION CAPPED AT VISION GLAZING